

Other Special Bridge Inspection Report

NBI Bridge No.: 04085

Route U.S. 281 over S. CANADIAN RIVER
Canadian County



Prepared for:

Oklahoma Department of Transportation

Field Division 04

Inspection Date:

11/11/2014



Report Prepared By:

BURGESS & NIPLE, INC.

5085 Reed Rd.
Columbus, Ohio 43220
614-459-2050

BURGESS & NIPLE
Engineers ■ Surveyors ■ Planners

OKLAHOMA DEPARTMENT OF TRANSPORTATION -

Bridge Inspection Report

Suff. Rating: 34.9
SD

Health Index :
53.8

NBI No.: 04085

Structure No.: 0902 0000 X

Local ID: -1

IDENTIFICATION
Description:
38-100' PONY TRUSS & 2-36' 1-BM. SPANS (BRIDGEPORT BR.)
1. State: Oklahoma 2. SHD District: Division 4
3. County Code: CANADIAN 4. Place Code: Unknown
Admin. Area: LT Snooper Truss
5. Inventory Route (Route On Structure): 1 - 2 - 1 - 00281 - 0
6. Feature Intersected: S. CANADIAN RIVER
7. Facility Carried: U.S. 281 U.S. 281
9. Location: CADDO CANADIAN CL 11. Mile Post: 0.000 mi
13. LRS Inv. Route./ Subroute.: 0902 0000 01
16. Latitude: 35 32 25.00 17. Longitude: 098 19 22.00
98. Border Br. Code: Unknown (P) % Resp.: 0 99. Border Br. #: Unknown

STRUCTURE TYPE AND MATERIALS
43. Main Span Material and Design Type
Steel Truss-Thru
44. Approach Span Material and Design Type
Steel Stringer/Girder
45. No. of Spans Main Unit: 38 46. No. of Approach Spans: 2
107. Deck Type: 1 Concrete-Bitum-in-Place
108A. Wearing Surface: 6 Bituminous
108B. Membrane: 8 Unknown
108C. Deck Protection: 8 Unknown

AGE AND SERVICE
27. Year Built: 1933 106. Year Reconstructed: Unknown
28A. Lanes on: 2 28B. Lanes Under: 0 19. Detour Length: 11.8 mi
29. ADT: 1100 30. Year of ADT: 2012 109. Truck ADT %: 16
42A. Type of Service on: 1 Highway
42B. Type of Service under: 5 Waterway

GEOMETRIC DATA
10. Inv. Rte. Min. Vert. Clr.: 328.1 ft
32. Approach Roadway Width (W/ Shoulders): 30.0 ft
Deck Area: 102,364.8 sq. ft 33. Median: 0 No median
34. Skew: 0 35. Structure Flared: 0 No flare
47. Inv. Rte. Total Horiz. Clr.: 24.0 ft
48. Length Maximum Span: 100.1 ft 49. Structure Length: 3,937.0 ft
50A. Curb/Sdwk Width L: 1.0 ft 50B. Curb/Sidewalk Width R: 1.0 ft
51. Width Curb to Curb: 24.0 ft 52. Width Out to Out: 26.0 ft
53. Minimum Vertical Clearance Over Bridge: 328.1 ft
54A/54B. Min. Vert. Underclearance: N Feature not hwy or RR 0.0 ft
Meas. N/E S/W
-1 -1 -1 -1 -1 -1
Post. DO NOT U DO NOT U DO NOT U DO NOT U DO NOT U DO NOT U
55A/55B. Minimum Lateral Underclearance R: N Feature not hwy or RR 327.8 ft
56. Minimum Lateral Underclearance L: 327.8 ft

INSPECTION
Type Insp Req. Insp Done Freq. Insp. Date. Next Insp.:
NBI: N 24 11/20/2013 11/20/2015
FC Freq.: Y N 24 11/20/2013 11/20/2015
UW Freq.: N N NA NA NA
OS Freq.: Y Y 24 11/11/2014 11/20/2016

CLASSIFICATION
12. Base Hwy Network: On Base Network 20. Toll Facility: 3 On free road
21. Custodian: 01State Highway Agency 22. Owner: 01State Highway Agency
26. Functional Class: 06 Rural Minor Arteri 37. Historical Sig.: 2 Br eligible for NRHP
100. Defense Highway: 0 Not a STRAHNET h 101. Parallel Structure: No || bridge exists
102. Dir. of Traffic: 2 2-way traffic 103. Temp. Structure: Not Applicable (P)
104. Highway System: 0 Not on NHS 105. Fed. Land Hwy 0 N/A (NBI)
110. National Truck Network: 0 Not part of na 112. NBIS Length: Long Enough

CONDITION
58. Deck: 5 Fair 59. Super.: 4 Poor 60. Sub.: 5 Fair
62. Culvert: N N/A (NBI) 61. Channel/Channel Protection: 5 Bank Prot Eroded
Flowline Notes:
[11/2014] FL to top of curb = 29.7' @ pier 9 east column
[2013] FL to top of curb = 30.1' measured @ pier 9 east column
[2011] FL to top of curb = 24.8' measured @ pier 9 east column

LOAD RATING AND POSTING
31. Design Load: 2 M 13.5 (H 15) 41. Posting status: A Open, no restriction
63. Op. Rating Method: 1 LF Load Factor-Ton Alt. Op. Rating Meth.: 1 LF Load Factor-To
64. Operating Rating (H / HS / 3-3): 24.4 36.3 65.4
66. Inventory Rating (H / HS / 3-3): 14.5 21.8 37.7
65. Inv. Rating Method: 1 LF Load Factor-Ton Alt. Inv. Rating Meth.: 1 LF Load Factor-To
70. Posting: 5 At/Above Legal Loads Date Rated: 3/25/2014

PROPOSED IMPROVEMENTS
94. Bridge Cost: \$6,781,689 75. Type of Work: 31 Repl-Load Capacit
95. Roadway Cost: \$4,500,000 76. Lgth. of Improvement: 3,937.0 ft
96. Total Cost: \$11,920,275 114. Future ADT: 1760
97. Year of Cost Est.: 2007 115. Year of Future ADT: 2032

NAVIGATION DATA
38. Navigation Control: Permit Not Required
39. Vertical Clearance: 0.0 ft 40. Horizontal Clearance: 0.0 ft
111. Pier Protection: 1 Not Required 116. Lift Bridge Vert. Clear.: 0.0 ft

APPRAISAL
36A. Bridge Rail: 0 Substandard 36C. Approach Rail: 0 Substandard
36B. Transition: 0 Substandard 36D. Approach Rail Ends: 0 Substandard
67. Str. Evaluation: 4 Minimum Tolerable 68. Deck Geometry: 4 Tolerable
69. Underclearance, Vertical and Horizontal: N Not applicable (NBI)
71. Waterway Adequacy: 4 Tolerable
72. Approach Alignment: 6 Equal Min Criteria
113. Scour Critical: 7 Countermeasures

200c. Temperature: 30
200d. Weather: CLEAR
201. Structural Steel ASTM Desig.: -1 -1
202. Waterproof Membrane: -1
Date Installed: 1/1/1901
203. Type Exp. Dev.: Sliding Plate
204. Type of Handrail: Steel Post and Rail
205. Material and Quantity: 10.0
208. Type of Abutment: Pedestal
Type of Foundation: Natural Foundation Matl.
209. Type of Pier / Found.: 2 Piers Yes
No Piling or Drilled Shaft
210. Foundation Elev. -1.0 -3.0
-3.0 -3.0 -1.0
211. Wear. Surf. Prot. System: None
Date Installed: 1/1/1901
213. Utilities Attached: -1
-1 -1 -1
-1 -1 -1

214a. Posted Weight Limit: NR
b. Posted Speed Limit: -1
c. Narrow/One Lane Bridge sign: -1
d. Vertical Clearance Sign: NO
Advanced Warning Sign: NO
Min. Measured Clearance: -1
Max. Measured Clearance: -1
e. Navigation Lights: NO
Working/Not Working: NO
215. Overpass: C - US Highway
221. Substructure Cond. (U/W): -
222. Fill over RCB: -1
223. Appr. Slab/Rdwy Cond.: Satisfactory
224. Critical Feature Type: 1
225. Paint Type: Red Lead Ready
Overcoat: 0
226. Date Painted: -1
227. Paint Coloring: Silver
233. Deck Forming: -
236. Deck Cleaning: -1
238. School Bus Rte: Current and Desired Route
240. Appr. Roadway Type: Concrete

243. Girder Spacing/Number: -1.0 / -1
244. Span Lengths:
-1 -1 -1
-1 -1 -1
245. Girder Depth: 48.000
246. Type of Overlay: AC Over
246. Overlay Thickness: 3.0
246. Overlay Date: 12/4/2003
246. Overlay Depth Changed > 1"? -
247. Protective Systems: 1: -
2: - 3: -
4: - 5: -
248. No. of Field Splices w/ Corrosion: -1
249. Scour Crit. POA exists?: -
250. Culvert Headwall Dist.: -1.0
254. Thru Truss Type: Pony
256. Chan. Profile Up/Down Stream?: -
257a. OkiePROS Auto. Truck Routing: Yes
258. Plans w/ found. are in file at ODOT
259. Scour Eval. is in file at ODOT
263. Interchange at Intersection N
264. Interstate Milepoint -1.00

OKLAHOMA DEPARTMENT OF TRANSPORTATION -**Bridge Inspection Report**NBI No.: **04085**

Structure No.: 0902 0000 X

Local ID: -1

Suff. Rating: 34.9
SDHealth Index :
53.8

Inspection Date: 11/11/2014 Reported By: DPOORMAN

Invoice No.: -1 Inspected With: -1

Agency :

Structure / Inspection Notes

(38) 100-foot pony trusses with (2) 36-foot beam approach spans.

O/S Inspection Items: Inspect cracks in stringer web copes*, stringer connection angles*, floor beams web copes*, lower chord gusset plates above bearings* for growth; Stringer connections at end floor beams for additional loss or broken rivets*; Pier beams and supplemental pier beams at piers 1 and 39 for distress; Sweep in end floor beams where stiff leg repairs have not been installed*; Misalignment of WU1U2 sp 37; Stringer 5 section loss at end floor beams. *See attached spreadsheet with crack locations/lengths, broken rivets, and floor beam sweep where stiff leg repairs have not been installed.

Former Smart Flag 364 (Steel Out-of-Plane Compression Member) was placed in Condition State 3 with the following note: 'FX- West truss U1U2 and L0U1 in span 37 is bowed globally to the west. Several above deck truss members have local bends due to impact damage.'

CX findings include: cracks in the end gusset plates above the bearings: span 2, L0, east truss, 15 1/8"; span 29, L5, east truss, 10". Sweeps in the end floor beams: span 25, floor beam 5, 7/16"; span 38, floor beam 5, 5/8"; span 39, floor beam 0, 5/8". These findings were discussed with Wes Kellogg and a letter was sent on 11/12/2014.

CX - Cracks in the end GP's above the bearings: span 2, L0, east truss, 15 1/8"; span 29, L5, east truss, 10". Sweeps in the end floor beams: span span 25, floor beam 5, 7/16"; span 38, floor beam 5, 5/8"; span 39, floor beam 0, 5/8"

PX - Reinforce the damaged concrete bridge railing in spans 1 and 40; Seal cracks in the asphalt wearing surface; Reinstall missing elastomeric pads/shims under beams at supplemental pier beams over piers 1 and 39; Drill crack tips in stringers and floor beams that grow significantly; Repair cracks in stringer connection angles by adding seat brackets below stringer; Repair section loss in stringer and floor beam webs; Reposition rotated shim plate at pier 26 stiff leg; Strengthen the horizontal shear planes of the end lower chord gusset plates at east L0 in spans 2 and 20 and east L5 in span 29; Replace sheared rivets in the vertical connection, upper chord, and end post at west U1 in spans 31 and 37; Grind out notches and cuts in inboard flange and gusset plate at west U1L2, span 31; Removing pack rust and caulk/paint along edges of end gusset plates; Cleaning and painting steel below deck within 5 feet of the joints; Add rip rap around pier 9; Install pressure relief joints in both approaches.

FX - Monitor: Pack rust/section loss in truss members at railing conn's; Deck, joints, and end floor beams for further distress due to possible deck growth; Spalls/reinforcing in soffit for further deterioration; Cracks at floor beam copes for growth; Stitch welds for strengthening angle at floor beam 0, span 2 for cracking; Corr holes through the floor bracing gusset plates for cracks; Bowed members near west U1, span 37 for distress; Impact damage on UC and truss web members for additional misalignment and development of cracks; Bowed GP's near bearings for distress; Lower chord section loss at floor system bracing connections, splices, and adjacent to stay/batten plates; Bullet strike damage to east truss span 4 members/gussets.

Additional
Elements

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 1 - End view looking north

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 2 - Elevation looking northwest

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 3 - Looking southwest at span 24, floor beam 0 connection to east truss. Note: Crack has grown 1/16-inch and is now 4 1/16 inches.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 4 - Looking east at span 25 floor beam 5, above pier 25. Note: 7/16-inch sweep without stiff leg.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 5 - Looking north at span 25, floor beam 5 connection to east truss. Note: The crack at the connection to the east truss has grown 1/2-inch and is now 6 3/4 inches long.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 6 - Looking north at span 30, floor beam 1 connection to the west truss. Note: Crack has grown 1/8-inch and is now 1/2 inch long.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 7 - Looking north at span 35, floor beam 5 connection to the east truss. Note: The crack has grown 1/16-inch and is now 2 13/16 inches long.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 8 - Looking east at span 38, floor beam 5 over pier 38. Note: 5/8-inch sweep to the south.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 9 - Looking east at span 39, floor beam 0 above pier 38. Note: 5/8-inch sweep to the north.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 10 - Looking northeast at span 27, stringer 1 at the south face of floor beam 1. Note: Crack has grown 1/2-inch and is now 7/8 inch long.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 11 - Looking east at span 32, stringer 5 at floor beam 0. Note: Stringer cope crack has grown 1/8-inch and is now 5/8 inch long.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 12 - Looking northwest at span 33, stringer 1 connection to floor beam 5. Note: Stringer cope crack has grown 1/8-inch and is now 1 1/4 inch long.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 13 - Looking southwest at span 36, stringer 4 connection to floor beam 0, east connection angle. Note: Stringer connection angle crack has grown 1/8-inch and is now 4 1/8 inches long.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 14 - Looking northwest at span 2, L0, east truss, inboard gusset plate. Note: Crack has grown 5 7/8 inches since 2013 bringing the crack to 15 1/8 inches total length.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 15 - Looking north at span 2, L0, east truss, inboard gusset plate. Note: Crack has grown 5 7/8 inches since 2013 bringing the crack to 15 1/8 inches total length.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 16 - Looking west at span 8, east truss, L0 inboard gusset plate. Note: Crack has grown 1/2 inch and is now 7 1/4 inches long.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014




Photograph 17 - Looking southwest at span 17, east truss, L5 inboard gusset plate. Note: Crack has grown 3/4 inch and is now 9 inches long.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 18 - Looking northeast at span 20, east truss, L0 inboard gusset plate. Note: crack has grown 3 1/2 inches and is now 6 1/2 inches long.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 19 - Looking southwest at span 29, east truss, L5 inboard gusset plate. Note: Crack has grown 3 3/4 inches to 10 inches.

NBI #	Structure #	County	Fac. Carried	Fac. Intersected	Insp. Date
04085	0902 0000 X	Canadian	U.S. 281	S. CANADIAN RIVER	11/11/2014



Photograph 20 - Looking northwest at span 30, east truss L0 inboard gusset plate. Note: New 4 3/4-inch long crack.

Appendix A: Stringer Cope Cracks

Span	Floor Beam	Floor Beam Face	Stringer	Length (in.)	Comment
2	0	North	5	7/8	
2	2	South	1	3/8	
2	4	South	1	1/8	
2	5	South	1	3/8	
3	0	North	1	1 1/4	
3	0	North	5	1/2	1/8" growth (2013)
3	5	South	1	3/8	
4	0	North	1	3/8	
4	2	South	5	1/4	
4	5	South	5	1 1/2 (drilled)	
5	0	North	5	1/2	
6	2	North	1	1/8	New crack (2013)
6	3	North	1	1/4	
7	0	North	5	2 1/4	
7	5	South	1	1/2, 3/8	Two diagonal cracks (2013)
7	5	South	5	3/4	
8	5	South	1	1 1/8	
9	1	North	1	1/4	
9	3	North	1	1/8	3/8" no growth from previous paint mark (2013)
9	3	South	1	3/8	
9	5	South	1	3/4	New crack (2014)
10	2	North	1	5/8	
10	5	South	5	7/8	
11	0	North	5	9/16	
12	5	South	1	1 1/2	1-1/2" long crack splits into multiple cracks (up to 1-1/2" additional length, others 3/16" long) (2013)
13	5	South	5	5/8	1/8" growth (2013)
14	0	North	5	1 3/8	1/8" growth and 1/4" corrosion hole (2013)
14	5	South	1	1 1/4	
15	0	North	1	1/8, 1/8	
16	4	North	5	1/2	
16	5	South	5	1/4	New crack (2013)
17	0	North	5	1	
17	3	North	1	1/16	
18	0	North	1	1/2	
18	2	South	1	3/8	
18	5	South	1	3/4	
19	0	North	5	1/2	
19	5	South	3	3/4	
19	5	South	5	1-1/4	1/4" growth (2013)
20	1	North	5	1/8	
20	2	North	1	1/2	

* Bolded and highlighted rows show new or changed comments.

Appendix A: Stringer Cope Cracks

Span	Floor Beam	Floor Beam Face	Stringer	Length (in.)	Comment
20	2	South	1	3/4	
20	4	North	5	1/8	
20	5	South	1	1/8	
21	0	North	5	7/8	1/8" growth (2013)
21	3	North	1	1/8	New crack (2013)
21	4	South	1	1/8	
23	1	South	5	3/16	New crack (2013)
25	0	North	5	3/4	
25	2	South	1	1/4	
26	3	North	1	3/16	
26	5	South	1	2 1/2	
27	1	North	1	3/8	
27	1	South	1	7/8	New crack (2013), 7/8", 1/2" growth (2014)
27	1	South	5	1/4	1/8" growth (2013)
27	2	South	1	3/16	
28	1	North	1	3/16	
28	2	North	1	5/8	
28	2	South	1	1/4	
28	2	North	1	1/2	New crack (2013)
28	5	South	1	5/8	
30	1	South	5	1/2	
30	4	North	5	1/2	On east face of stringer, crack measures 1/4" (2013)
31	2	North	1	1/4	
32	2	South	1	1/4	
32	4	South	1	1/4	
32	5	South	1	1/4	
32	0	North	5	5/8	New crack (2013), 5/8", 1/8" growth (2014)
33	2	South	1	1/8	New crack (2013)
33	5	South	1	1 1/4	1 1/4", 1/8" growth (2014)
34	1	South	1	1/4	
34	2	South	1	1/4	
34	5	South	1	1/2	
35	0	North	1	1/2	
35	4	South	1	1/8	
36	2	South	1	3/4	
36	0	North	1	1/4	New crack (2013)
37	0	North	5	1/2	
37	3	North	1	1/4	
38	2	North	1	3/4	
38	2	South	1	5/8	
38	5	South	1	1/2	

* Bolded and highlighted rows show new or changed comments.

Appendix A: Stringer Cope Cracks

Span	Floor Beam	Floor Beam Face	Stringer	Length (in.)	Comment
39	1	North	1	1/8	New crack (2013)
39	1	South	1	1/2	
39	3	South	1	3/8	

* Bolded and highlighted rows show new or changed comments.

Appendix B: Stringer Connection Cracks

Span	Floor Beam	Floor Beam Face	Stringer	Stringer Face	Length (in.)	Comment
2	0	North	2	West	3 1/4	
3	5	South	4	West	2 1/2	
4	0	North	2	West	3	
5	5	South	3	East	3 1/4	
8	0	North	3	West	3 1/2	
9	5	South	3	East	1 1/4	New crack (2013)
9	5	South	3	West	3 1/2	
10	0	North	3	West	3	
12	0	North	2	East	3	
13	5	South	4	East	4	
15	5	South	4	West	3 5/8	
17	5	South	4	East	4 3/4	
18	0	North	3	East	2 3/4	1/4" growth (2013)
18	0	North	4	East	2 3/4	
22	0	North	1	East	3 3/4	
22	0	North	3	East	3 1/2	
22	0	North	4	East	2 3/4	
23	5	South	4	West	3 1/2	
24	0	North	2	West	2 3/4	
24	0	North	3	East	4	
24	0	North	3	West	4	
24	0	North	4	East	3 1/4	
25	5	South	2	West	3 1/4	
25	5	South	3	West	4 1/2	
25	5	South	4	West	3 1/2	
25	5	South	5	West	6	
26	0	North	2	East	2 3/4	
26	0	North	2	West	3 1/4	
26	0	North	3	East	5 3/8	
26	0	North	3	West	2 3/8	
26	0	North	4	East	3 1/2	1/4" growth (2013)
27	5	South	3	East	2 1/2	
27	5	South	3	West	3 3/4	
27	5	South	4	West	4 1/4	
28	0	North	2	East	4	
28	0	North	3	East	3 3/4	
29	5	South	3	West	4	
29	5	South	4	East	1 1/2	

* Bolded and highlighted rows show new or changed comments.

Appendix B: Stringer Connection Cracks

Span	Floor Beam	Floor Beam Face	Stringer	Stringer Face	Length (in.)	Comment
30	0	North	2	East	5 5/8	
30	0	North	3	East	4 1/2	
30	0	North	4	East	3 1/2	
30	1	South	5	West	9/16	New crack (2013)
31	5	South	4	East	3 3/4	
31	5	South	4	West	6 1/8	
33	5	South	3	West	4	
33	5	South	4	West	7	
34	0	North	2	East	3 1/2	
34	0	North	2	West	2	
34	0	North	3	West	2 1/4	
34	5	South	5	West	4 1/2	
35	5	South	3	West	4 1/4	
35	5	South	4	West	4	
36	0	North	2	West	2 7/8	
36	0	North	3	West	2	
36	0	North	4	East	4 1/8	1/8" growth (2014)
38	0	North	2	West	2 1/8	
38	0	North	3	West	2 1/2	
39	5	South	4	West	4 5/8	1/8" growth (2013)

* Bolded and highlighted rows show new or changed comments.

Appendix C: Missing Stringer Rivets

Span	Floor Beam	Floor Beam Face	Stringer	Number	Comment
2	0	North	2	1	All shanks still in shear plane unless noted otherwise.
2	0	North	3	2	
4	0	North	2	1	
4	1	South	2	1	
4	3	South	3	1	
5	1	North	2	1	
5	1	North	3	1	
5	2	North	2	1	
5	5	South	4	1	
6	0	North	2	2	East rivet shank no longer in shear plane.
6	0	North	3	1	East rivet shank no longer in shear plane.
6	1	North	2	1	
6	2	North	2	2	
7	1	North	2	1	
7	2	North	2	2	
7	2	North	3	1	
7	5	South	3	2	
7	5	South	4	2	
8	0	North	2	2	
8	0	North	3	1	Rivet shank is welded to connection angle
8	1	North	2	1	
9	1	North	2	2	
9	4	South	4	1	
9	5	South	4	2	
10	0	North	2	2	
10	0	North	3	1	
10	1	North	2	2	
10	1	North	3	2	
10	4	South	4	1	
11	1	North	2	1	
11	4	South	4	2	
11	5	South	3	2	Both shanks not in shear plane.
11	5	South	4	2	
12	0	North	3	2	
12	0	North	4	1	
13	2	North	2	2	
14	0	North	2	2	Both shanks not in shear plane.
15	5	South	3	2	
15	5	South	4	1	
16	0	North	2	2	

* Bolded and highlighted rows show new or changed comments.

Appendix C: Missing Stringer Rivets

Span	Floor Beam	Floor Beam Face	Stringer	Number	Comment
16	0	North	3	1	
17	5	South	4	1	
18	0	North	2	2	Both shanks not in shear plane.
18	0	North	3	1	
18	4	South	3	1	
20	0	North	1	1	
20	0	North	2	1	
22	0	North	2	2	Previously only 1
22	0	North	3	1	
23	2	North	2	1	
23	4	North	4	1	
24	0	North	2	2	
24	4	South	4	2	
25	2	North	2	1	
25	5	South	4	1	Shank not in shear plane.
26	0	North	2	1	
28	1	North	2	1	
29	1	North	2	2	
30	0	North	3	1	
31	5	South	3	2	
32	0	North	2	2	
32	0	North	3	1	
33	1	North	2	1	
33	5	South	3	1	
34	0	North	3	1	
34	1	North	2	1	
34	1	North	3	1	
35	2	North	2	2	
35	4	South	4	1	
35	5	South	3	2	
35	5	South	4	1	
36	0	North	2	1	
36	0	North	3	1	
36	1	North	2	2	
36	1	North	3	2	
36	4	South	3	1	
37	1	North	2	1	
37	2	North	2	1	
37	5	South	3	2	
37	5	South	4	1	

* Bolded and highlighted rows show new or changed comments.

Appendix C: Missing Stringer Rivets

Span	Floor Beam	Floor Beam Face	Stringer	Number	Comment
38	0	North	2	2	Shank no longer in shear plane, east connection angle.
38	0	North	3	2	Shank no longer in shear plane, east connection angle.
38	1	North	2	1	
39	5	South	3	1	

* Bolded and highlighted rows show new or changed comments.

Appendix D: Stringer Loss

Span	Floor Beam	Floor Beam Face	Stringer	Description
2	0	North	1	3/4" diameter
4	0	North	5	1 1/4" diameter with 1/4" crack
5	5	South	5	1" diameter with horizontal crack, 1/2"L, and vertical crack, 3/8"L
6	0	North	1	1-1/2" diameter with vertical crack, 3/4"
6	0	South	5	1 3/8" diameter, 1/4" vertical crack
9	1	South	5	2 1/4" x 1"
9	5	South	1	2 3/4"H x 1" with 3/8" vertical crack and 3/8" diagonal crack
9	5	South	5	1" x 1 1/4" with 1/8" crack.
10	0	North	5	1/2" diameter hole with 3"H x 3/16", 4"H x 1/8", and 3"H x 1/16" pitting extending below the hole
11	5	South	5	5/8" diameter with 7/8" long crack
12	0	North	1	1" diameter with 1/4" vertical crack.
12	0	North	5	1-1/8"H x 5/8"
12	1	North	5	1"H x 3/4"W
13	5	South	1	1 1/2" x 5/8" with 1/8" loss over top half of web depth, outboard face (20% total web loss).
15	5	South	5	7/8" diameter at cope & 1" diameter below connection angle
16	0	North	5	4-1/4"H x 1-1/2" hole with two cracks (5/8" & 1/4")
17	4	North	5	2 1/2" x 1" with 3/8" long crack
17	5	South	1	Two holes: 1 1/2"W x 1/2"H and 1/2"H hole with 5/8" crack
17	5	South	5	2 1/4"H x 1" with 1/2" long crack
18	0	North	5	2 1/2"H x 1"W hole with 3/16" pitting for 7"H
19	5	South	1	1/2" hole with 3/4" crack
19	5	South	5	7 1/2"W x 4"H
20	0	North	5	1 1/4" diameter
21	5	South	1	1 1/4" x 1/4"
21	5	South	5	2 1/2"H x 1 1/2"W with 3-7/8" long crack
22	0	North	1	2" x 1/2"
23	5	South	5	2 3/4"H x 1/2"W
24	0	North	1	1"H x 1/2" W with 3/16" max pitting over 6" below hole
24	0	North	5	10 1/2"W x 2"H with 1/16-1/8" remaining full height at edge of connection angle
24	5	South	5	1" diameter
25	2	North	5	1/2" diameter
25	5	South	1	2"H x 5/8"W with 5/8" crack
25	5	South	5	1/8" section loss, full height.
26	0	North	1	1/2" diameter
26	0	North	5	2" x 1/2"

* Bolded and highlighted rows show new or changed comments.

Appendix D: Stringer Loss

Span	Floor Beam	Floor Beam Face	Stringer	Description
27	5	South	1	3"H X 1"W with 1" horizontal crack and 3/16" vertical crack
29	4	South	5	5/8" dia corrosion hole in stringer cope
29	5	South	5	1 1/2"H X 1"W with two cracks, 1" crack extends cope to hole & 1" crack below hole
30	0	North	5	1 1/2" x 1 1/2"
31	5	South	5	1 1/2" H x 1" W & 1 1/4" H x 1" W
34	3	South	5	3" H x 3/4" W
34	4	South	5	1" x 1 1/4"
35	5	South	5	5" W X 1 3/4" H
36	0	North	5	2-1/2" H x 1-1/4" W with 7/8" vertical crack. Also, 1/4" pitting for 3" H and 1/8" pitting for remaining height. Approx 50% section loss to this location. Heavy rivet head loss on stringer connection rivets on outside face due to laminating corrosion. Additional corrosion hole is 3" W x 1-1/4"H in lower web of stringer.
38	0	North	5	2"H x 3/4"H hole at cope with 1/8" average (3/16" max) section loss full height on outboard face
38	5	South	5	1 1/2"H X 4 1/2"W below connection angle and 1/2" cope crack
39	0	North	5	1/4" X 1/2"
39	1	South	5	1/2"H x 1/4"W hole within 1-1/16" crack at cope, also 1/8" average full height section loss.
39	5	South	1	1" diameter with 1/2" crack

* Bolded and highlighted rows show new or changed comments.

Appendix E: Floor Beam Sweep

Span	Floor Beam	North / South	Sweep	Stiff Leg	Comment
1	pier 1			N	Sister pier girder added due to severe sweep
2	0			N	
2	5			N	
3	0	North	1/2	Y	Stiff leg installed
3	5	South	1/4	Y	Stiff leg installed
4	0	North	1/4	Y	Stiff leg installed
4	5	South	1/4	Y	Stiff leg installed
5	0	North	3/4	Y	Stiff leg installed
5	5			N	
6	0			N	
6	5	South	1/2	Y	Stiff leg installed
7	0	North	1/2	Y	Stiff leg installed
7	5			N	
8	0	North	1/4	Y	Stiff leg installed
8	5	South	1/2	Y	Stiff leg installed
9	0	North	3/8	Y	Stiff leg installed
9	5			N	
10	0			N	
10	5	South	1/2	Y	Stiff leg installed
11	0	North	5/8	Y	Stiff leg installed
11	5	South		N	
12	0	North	1/4	Y	Stiff leg installed
12	5	South	5/8	Y	Stiff leg installed
13	0	North	1/2	Y	Stiff leg installed
13	5	South	3/16	Y	Stiff leg installed
14	0	North	5/8	Y	Stiff leg installed
14	5	South	1/2	Y	Stiff leg installed
15	0	North	5/8	Y	Stiff leg installed
15	5	South	3/16	Y	Stiff leg installed
16	0	North	3/16	N	No change. No stiff leg at floor beam.
16	5	South	3/4	Y	Stiff leg installed
17	0	North	1/2	Y	Stiff leg installed
17	5	South	1/4	Y	Stiff leg installed
18	0	North	5/16	Y	Stiff leg installed
18	5	South	3/4	Y	Stiff leg installed
19	0	North	5/8	Y	Stiff leg installed
19	5			N	
20	0			N	
20	5	South	7/8	Y	Stiff leg installed
21	0	North	5/8	Y	Stiff leg installed

* Bolded and highlighted rows show new or changed comments.

Appendix E: Floor Beam Sweep

Span	Floor Beam	North / South	Sweep	Stiff Leg	Comment
21	5	North		N	
22	0	North	1/4	Y	Stiff leg installed
22	5	South	1/8	N	Stiff leg installed
23	0	North	1/2	Y	
23	5			Y	Stiff leg installed
24	0	North	1/4	Y	Stiff leg installed
24	5	South	3/4	Y	Stiff leg installed
25	0	North	3/8	Y	Stiff leg installed
25	5	North	7/16"	N	CX - Add Stiff Leg, Sweep is 7/16", no stiff leg repair
26	0	North	3/8	Y	Stiff leg installed
26	5	South	1/2	Y	Stiff leg installed
27	0	North	3/4	Y	Stiff leg installed
27	5	South	5/8	Y	Stiff leg installed
28	0	North	1/2	Y	Stiff leg installed
28	5	South	3/4	Y	Stiff leg installed
29	0	North	3/4	Y	Stiff leg installed
29	5			N	
30	0			N	
30	5	South	7/8	Y	Stiff leg installed
31	0	North	1/2	Y	Stiff leg installed
31	5			N	
32	0			N	
32	5	South	3/4	Y	Stiff leg installed
33	0	North	3/8	Y	Stiff leg installed
33	5			N	
34	0			N	
34	5	South	3/4	Y	Stiff leg installed
35	0	North	1/2	Y	Stiff leg installed
35	5			N	
36	0			N	
36	5	South	5/8	Y	Stiff leg installed
37	0	North	1/2	Y	Stiff leg installed
37	5			N	
38	0			N	
38	5	South	3/8	N	CX - Add Stiff Leg (2013), Sweep now 5/8", no stiff leg repair
39	0	North	3/8	N	CX - Add Stiff Leg (2013), Sweep now 5/8", no stiff leg repair

* Bolded and highlighted rows show new or changed comments.

Appendix E: Floor Beam Sweep

Span	Floor Beam	North / South	Sweep	Stiff Leg	Comment
39	5			N	
40	pier 39				Sister pier girder added due to severe sweep

* Bolded and highlighted rows show new or changed comments.

Appendix F: Floor Beam Loss

Span	Floor Beam	Location	Comment
3	5	Between stringers 3 and 4	1 1/2" diameter
4	0	At stringer 4	14" L x 1" H
5	5	Between stringers 3 and 4	2" H x 1" W
5	5	Between stringers 1 and 2	3/4" diameter and 1" H x 2" W
6	0	Between stringers 3 and 4	1" H x 14" W
6	0	Between stringers 1 and 2	6" W x 1-1/4" H
7	2	At E Truss	1/2" U-shaped corrosion hole with crack.
11	5	Between stringers 4 and 5	5 through holes, 4"Hx1-1/2" and four 3/8" diameter
11	5	Near stringer 3	4 1/2" W x 1 1/2" H
12	0	Near stringer 4	1.5" W x 1" H, 3.5" W x 3/4" H, 2.5" W x 1" H
12	3	At E Truss	1" H x 1/2" W
15	3	At E Truss	9/16" diameter with 1/4" corrosion crack
15	4	At E Truss	1/2"W x 1/4"H corrosion hole in floor beam cope.
15	5	Between stringers 1 and 2	6" W x 2" H
16	4	East truss	3-1/2"H x 4-1/4"W
18	2	At E Truss	1"H x 5/8"W, with 3/4" crack, with 1/4" diameter corrosion hole.
22	5	Near stringer 4	1-1/2" W x 3/4" H in lower web
23	0	At E truss	1-1/8" H x 5/8" W in lower web
24	0	Between stringer 1 & west truss	3/4" diameter in lower web
25	2	At E Truss	2 5/8" H x 1 3/4" W corrosion hole in floor beam cope
26	3	At E Truss	1/2" corrosion hole in floor beam cope
27	0	Between stringer 1-2	1-3/4"W x 1"H
27	1	At W Truss	2" diam.
27	2	At E Truss	1 1/4" H x 1" W
28	3	At stringer 5	4" H x 3/4" W
29	5	Between stringers 2-3	2-1/4" W x 3/4" H
37	5	Between stringers 4 and 5	3/4" H X 2" W, multiple holes (3/4"H x 12"W)
38	0	At east truss connection	1 1/4" H x 3/4" W
38	0	Between stringers 4 and 5	3 corrosion holes between: 1" H x 5" W, 1" H x 1" W, 1" H x 1 1/2" W

* Bolded and highlighted rows show new or changed comments.

Appendix G: Floor Beam Cracks

Span	Truss	Floor Beam	Length (inch)
2	East	0	2 1/4
2	West	5	1 3/8
3	East	5	3 1/8
3	West	5	1 1/2
4	East	0	5
4	West	0	3
5	West	3	1/4
5	East	5	3
5	West	5	1
6	East	0	8
6	West	0	1 1/4
7	West	0	7/8
7	East	5	3
7	West	5	1 5/8
8	East	0	6 1/8
8	West	0	3 7/8
9	East	5	3
9	West	5	2 1/2
10	East	0	6 5/8
10	West	0	3
11	East	5	3
11	West	5	2 1/2
12	East	0	1 7/8
12	West	0	1 11/16
13	East	5	2 1/2
13	West	5	1 1/4
14	East	0	5 7/16
14	West	0	2 9/16, 1 5/8
14	East	1	7/16
15	East	5	4 3/4 with 3/16 lateral offset
15	East	3	1/4
16	East	0	3 3/4
16	West	0	3 5/8
16	East	1	1/2
16	West	1	1/2
17	East	4	3/8
17	West	4	1/2
17	East	5	3
17	West	5	3 1/8
18	East	0	5 1/8
18	West	0	3 3/8

* Bolded and highlighted rows show new or changed comments.

Appendix G: Floor Beam Cracks

Span	Truss	Floor Beam	Length (inch)
18	East	2	3/4
19	East	5	1 3/8
19	West	5	2 1/8
20	East	0	6 3/8
20	West	0	1 3/4
20	East	2	1/8
21	East	5	1 1/4
21	West	5	1 5/8
22	East	0	3 3/4 with 5/16 lateral offset in web
22	West	0	5 1/4
22	West	1	3/8
23	East	5	4
23	West	5	3/4
24	East	0	4 1/16, grew 1/16" (2014)
24	West	0	4 5/8
24	East	1	3/4
24	East	2	5/8
25	East	5	6 1/4 (2013), grew 1/2" to 6 3/4" (2014)
26	East	0	4 1/4
26	West	0	2 1/4
27	East	5	1 1/4
28	East	2	3/16
29	East	4	3/8
29	East	5	Two cracks: 4 7/8 & unk (continues under connection angle)
29	West	5	5/8
30	East	0	1 5/8
30	West	0	5/8
30	West	1	3/8" (2013), grew 1/8" to 1/2" (2014)
30	East	2	1
31	East	5	4 1/4
31	West	5	1
32	East	0	2
32	West	0	5/8
33	East	3	1/8 with 3/8 dia corrosion hole
33	East	5	3 1/4

* Bolded and highlighted rows show new or changed comments.

Appendix G: Floor Beam Cracks

Span	Truss	Floor Beam	Length (inch)
34	East	0	2
35	East	3	1/4
35	East	5	2 13/16, grew 1/16" (2014)
35	West	5	3 1/8
36	East	0	2 1/4
36	West	0	1 3/8
36	West	1	3/8
37	East	5	2
37	West	5	1 3/4
38	East	0	9" with 3/8" lateral offset (2013), grew 3/16" to 9 3/16" (2014)
38	West	0	3 1/2
38	West	1	3/8
38	East	2	9/16 vertical with 1/4 horizontal
38	West	4	1/8
39	West	1	1/8
39	East	4	1/4
39	West	4	1/4
39	East	5	3
39	West	5	1 1/2

* Bolded and highlighted rows show new or changed comments.

Appendix G: Floor Beam Cracks

Span	Truss	Panel Point	Length of Crack (in.)	Comment
2	East	L0	15 1/8	New (2013), 15 1/8", 5 7/8" growth (2014)
8	East	L0	7 1/4	1 1/4" growth. Welded angle repair (2013), 7 1/4", 1/2" growth (2014)
14	West	L0	4 1/2	1/2" growth. Welded angle repair (2013), No Change (2014)
17	East	L5	9 3/4	1/4" growth. Welded angle repair (2013), 9", 3/4" growth (2014)
19	West	L5	8 1/8	2 3/4" growth. Welded angle repair (2013), No Change (2014)
20	East	L0	6 1/2	New (2013), 6 1/2", 3 1/2" growth (2014)
24	East	L0	8	2 3/4" growth. Welded angle repair (2013), No Change (2014)
29	East	L5	10	New (2013), 10", 3 3/4" growth (2014)
30	East	L5	6 3/4	New (2014)
33	East	L5	13	1 1/2" growth. Welded angle repair (2013), No Change (2014)

* Bolded and highlighted rows show new or changed comments.

BURGESS & NIPLE

5085 Reed Road | Columbus, OH 43220 | 614.459.2050

Mr. Wes Kellogg, PE
Field Service Engineer
Oklahoma Department of Transportation
Bridge Division
200 NE 21st Street
Oklahoma City, OK 73105

Re: CX Repair Recommendation
NBI No.: 04085
S.H. 281 over S. Canadian River
Field Division 4

November 12, 2014

Wes:

As Ed Cinadr briefly discussed with you yesterday, we found the following CX issues on the above referenced bridge:

- Cracks in the truss gusset plate above the bearing:
 - Span 2, L0 east truss, inboard gusset (**photo 1**) – 15 1/8-inch long horizontal crack (crack has grown 5 7/8 inches since the 2013 inspection).
 - Span 29, L5 east truss, inboard gusset plate (**photo 2**) – 10-inch long horizontal crack (crack has grown 3 3/4 inches since the 2013 inspection).

We are recommending that these gusset plates be repaired by welding an angle between the inboard face of the gusset plate and the top flange of the lower chord inboard channel (similar to other recent repairs). In addition to these cracks, similar cracks were also observed at:

- Span 20, L0 east truss, inboard gusset plate (**photo 3**). This 6 3/4-inch long horizontal crack has grown 3 3/4 inches since the 2013 inspection.
- Span 30, L0 east truss, inboard gusset plate (**photo 4**). This 4 3/4" long horizontal crack was not previously noted. The crack is adjacent to that noted above in Span 29, L5 east truss.

Due to the rate of propagation, it is recommended that these cracks also be repaired.

- Sweeps in the floor beam bottom flange:
 - Span 25, floor beam 5 over pier 25 (**photo 5**) – 7/16-inch sweep to the north of the floor beam bottom flange.
 - Span 38, floor beam 5 over pier 38 (**photo 6**) – 5/8-inch sweep to the south of the bottom flange (this sweep was reported as 3/8 inch during the 2013 inspection).
 - Span 39, floor beam 0 over pier 38 (**photo 7**) – 5/8-inch sweep to the south of the bottom flange (this sweep was reported as 3/8 inch during the 2013 inspection).

We recommend that a stiff leg repair be installed at each of these floor beams.

The bridge runs southwest to northeast, but for the purposes of this letter and previous reports, is considered to run south-to-north. If the bridge is to reopen for an extended period of time, consideration should be given to strengthening all of the inboard L0 and L5 gusset plates and stiff legging all of the end floor beams which are not already retrofitted. Based on inspection findings over the past few cycles, it appears that these issues will continue to occur at similar locations with ongoing deterioration.

Feel free to contact me with any questions or comments you may have regarding this issue.

Sincerely,

BURGESS & NIPLE, INC.



Dale Poorman, PE
Team Leader

cc: Ed Cinadr, PE



Photo 1 – Looking northwest at span 2, L0 east truss, inboard gusset plate.
Note: 15 1/8-inch long horizontal crack above bearing pin.



Photo 2 – Looking southwest at span 29, L5 east truss, inboard gusset plate.
Note: 10-inch long horizontal crack above bearing pin.



Photo 3 – Looking northwest at span 20, L0 east truss, inboard gusset plate.
Note: 6 3/4-inch long horizontal crack above bearing pin.



Photo 4 – Looking northwest at span 30, L0 east truss, inboard gusset plate.
Note: 4 3/4-inch long horizontal crack above bearing pin.



Photo 5 – Looking east along floor beam 5, span 25 over pier 25. Note: 7/16-inch sweep of bottom flange to the north.



Photo 6 – Looking east along floor beam 5, span 38 over pier 38. Note: 5/8-inch sweep of bottom flange to the south.



Photo 7 – Looking east along floor beam 0, span 39 over pier 38. Note: 5/8-inch sweep of bottom flange to the north.