

# OKLAHOMA DEPARTMENT OF TRANSPORTATION -

# Bridge Inspection Report

Suff. Rating: 60.5  
ND

Health Index :  
98.0

NBI No.: 13688

Structure No.: 6602 0368EX

Local ID:-1

**IDENTIFICATION**  
Description: 100'-140'-210'-160'-100'-100' HL. TRUSS SPANS  
1. State: Oklahoma 2. SHD District: Division 8  
3. County Code: ROGERS 4. Place Code: Unknown  
Admin. Area: Unknown  
5. Inventory Route (Route On Structure) : 1 - 3 - 1 - 00066 - 0  
6. Feature Intersected: BIRD CREEK & RD. UNDER  
7. Facility Carried: S.H. 66 NB S.H. 66 NB  
9. Location: 3.3 MI N JCT I-44 11. Mile Post: 3.679 mi  
13. LRS Inv. Route./ Subroute.: -1 -1  
16. Latitude: 36 12 29.18 17. Longitude: 095 43 29.72  
98. Border Br. Code: Unknown (P) % Resp. : 0 99. Border Br. #: Unknown

**STRUCTURE TYPE AND MATERIALS**  
43. Main Span Material and Design Type  
Steel Truss-Thru  
44. Approach Span Material and Design Type  
Unknown (NBI) Unknown (P)  
45. No. of Spans Main Unit: 6 46. No. of Approach Spans: 0  
107. Deck Type: 1 Concrete-Cast-in-Place  
108A. Wearing Surface: 1 Monolithic Concrete  
108B. Membrane: 8 Unknown  
108C. Deck Protection: 8 Unknown

**AGE AND SERVICE**  
27. Year Built: 1956 106. Year Reconstructed: 1979  
28A. Lanes on: 2 28B. Lanes Under: 2 19. Detour Length: 0.1 mi  
29. ADT: 6750 30. Year of ADT: 2014 109. Truck ADT %: 7  
42A. Type of Service on: 1 Highway  
42B. Type of Service under: 6 Highway-waterway

**GEOMETRIC DATA**  
10. Inv. Rte. Min. Vert. Clr.: 15.8 ft  
32. Approach Roadway Width (W/ Shoulders): 37.1 ft  
Deck Area: 25,565. sq. ft 33. Median: 0 No median  
34. Skew: 0 35. Structure Flared: 0 No flare  
47. Inv. Rte. Total Horiz. Clr.: 29.8 ft  
48. Length Maximum Span: 210.0 ft 49. Structure Length: 824.7 ft  
50A. Curb/Sdwk Width L: 0.8 ft 50B. Curb/Sidewalk Width R: 0.8 ft  
51. Width Curb to Curb: 29.8 ft 52. Width Out to Out: 31.0 ft  
53. Minimum Vertical Clearance Over Bridge: 15.8 ft  
54A/54B. Min. Vert. Underclearance : H Hwy beneath struct 16.6 ft  
N/E S/W  
Meas. N1509 -1 E1502 S1509 -1 -1  
Post. DO NOT U DO NOT U DO NOT U DO NOT U DO NOT U -1  
55A/55B. Minimum Lateral Underclearance R: H Hwy beneath struct 15.1 ft  
56. Minimum Lateral Underclearance L: 327.8 ft

**INSPECTION**  
**Type Insp Req. Insp Done Freq: Insp. Date: Next Insp.:**  
NBI: N 24 11/17/2015 11/17/2017  
FC Freq.: Y N 24 11/17/2015 11/17/2017  
UW Freq.: N N NA NA NA  
OS Freq.: Y Y 24 11/16/2016 11/16/2018

**CLASSIFICATION**  
12. Base Hwy Network : Not on Base Network 20. Toll Facility: 3 On free road  
21. Custodian: 01State Highway Agency 22. Owner: 01State Highway Agency  
26. Functional Class: 17 Urban Collector 37. Historical Sig.: 2 Br eligible for NRHP  
100. Defense Highway: 0 Not a STRAHNET h 101. Parallel Structure: Right of || bridge  
102. Dir. of Traffic: 1 1-way traffic 103. Temp. Structure: Not Applicable (P)  
104. Highway System: 0 Not on NHS 105. Fed. Land Hwy 0 N/A (NBI)  
110. National Truck Network: 0 Not part of na 112. NBIS Length: Long Enough

**CONDITION**  
58. Deck: 5 Fair 59. Super.: 5 Fair 60. Sub.: 6 Satisfactory  
62. Culvert: N N/A (NBI) 61. Channel/Channel Protection: 6 Bank Slumping  
Flowline Notes:  
[11/19/2015] FL=59' to top of curb in span 3, panel point L3, east truss  
[12/14/2016] FL=57'1" to top of curb, Span 3, L3, east truss

**LOAD RATING AND POSTING**  
31. Design Load: 4 M 18 (H 20) 41. Posting status: A Open, no restriction  
63. Op. Rating Method: 1 LF Load Factor-Ton Alt. Op. Rating Meth.: 1 LF Load Factor-To  
64. Operating Rating (H / HS / 3-3) : 30.4 47.5 72.6  
66. Inventory Rating (H / HS / 3-3) : 16.8 28.5 41.4  
65. Inv. Rating Method: 1 LF Load Factor-Ton Alt. Inv. Rating Meth.: 1 LF Load Factor-To  
70. Posting: 5 At/Above Legal Loads Date Rated : 3/20/2014

**PROPOSED IMPROVEMENTS**  
94. Bridge Cost: \$3,226,224 75. Type of Work: 31 Repl-Load Capacity  
95. Roadway Cost: \$4,500,000 76. Lgth. of Improvement: 825.1 ft  
96. Total Cost: \$8,163,557 114. Future ADT: 10800  
97. Year of Cost Est.: 2009 115. Year of Future ADT: 2034

**NAVIGATION DATA**  
38. Navigation Control: Permit Not Required  
39. Vertical Clearance: 0.0 ft 40. Horizontal Clearance: 0.0 ft  
111. Pier Protection: Not Applicable (P) 116. Lift Bridge Vert. Clear.: 0.0 ft

**APPRAISAL**  
36A. Bridge Rail: 0 Substandard 36C. Approach Rail: 1 Meets Standards  
36B. Transition: 1 Meets Standards 36D. Approach Rail Ends: 1 Meets Standards  
67. Str. Evaluation: 5 Above Min Tolerable 68. Deck Geometry: 4 Tolerable  
69. Underclearance, Vertical and Horizontal: 9 Above Desirable  
71. Waterway Adequacy: 7 Above Minimum  
72. Approach Alignment: 8 Equal Desirable Crit  
113. Scour Critical: 8 Stable Above Footing

200c. Temperature: 64  
200d. Weather: CLEAR  
201. Structural Steel ASTM Desig.: -1 -1  
202. Waterproof Membrane : -1  
Date Installed : 1/1/1901  
203. Type Exp. Dev. : Modular  
Pourable  
204. Type of Handrail: Metal Railing (other)  
205. Material and Quantity : -1.0  
208. Type of Abutment : Cantilever  
Type of Foundation : Natural Foundation Matl.  
209. Type of Pier / Found.: 2 Piers No  
Concrete Piling  
210. Foundation Elev. -1.0 -1.0  
-1.0 -1.0 -1.0  
211. Wear. Surf. Prot. System : None  
Date Installed : 1/1/1901  
213. Utilities Attached : Communication  
-1 -1 -1  
-1 -1 -1

214a. Posted Weight Limit: NR  
b. Posted Speed Limit : 45  
c. Narrow/One Lane Bridge sign : NO  
d. Vertical Clearance Sign: YES  
Advanced Warning Sign : NO  
e. Navigation Lights : NO  
Working/Not Working : NO  
215. Overpass : B - State Highway  
221. Substructure Cond. (U/W) : -  
222. Fill over RCB: -1  
223. Appr. Slab/Rdwy Cond.: Satisfactory  
225. Paint Type : -  
Overcoat : Not Applicable  
226. Date Painted: -1  
227. Paint Coloring: -1  
233. Deck Forming: Conventional Forming  
238. School Bus Rte: Current and Desired Route  
240. Appr. Roadway Type: Asphalt/Bituminous

243. Girder Spacing/Number : -1.0 / -1  
244. Span Lengths :  
100 160 -1  
140 100 -1  
210 100  
245. Girder Depth : -1.000  
246. Type of Overlay : -  
246. Overlay Thickness : -1.0  
246. Overlay Date : 1/1/1901  
246. Overlay Depth Changed > 1"? No  
247. Protective Systems : 1: -  
2: - 3: -  
4: - 5: -  
248. No. of Field Splices w/ Corrosion : -1  
249. Scour Crit. POA exists?: No  
250. Culvert Headwall Dist.: -1.0  
256. Chan. Profile Up/Down Stream?: -  
257a. OkiePROS Auto. Truck Routing Yes  
258. Plans w/ found. are in file at ODOT:  
259. Scour Eval. is in file at ODOT:  
263. Interchange at Intersection: No Interchange  
264. Interstate Milepoint: -1.00

# OKLAHOMA DEPARTMENT OF TRANSPORTATION -

# Bridge Inspection Report

Suff. Rating: 60.5  
ND

Health Index :  
98.0

NBI No.: 13688 Structure No.: 6602 0368EX Local ID:-1

Inspection Date: 12/6/2016 Reported By: BDIETRICH

Invoice No.: -1 Inspected With: FJN, LWB

Agency :

## Structure / Inspection Notes

140-foot thru-truss (span 2), 210-foot thru-truss (span 3), 160-foot thru-truss (span 4) and three 100-foot pony trusses (Spans 1,5&6)

O/S Inspection Items Include: Cracks at stringer copes; Section loss/welded repairs to stringer and floor beam ends; Section loss to lower chord truss gusset plates; Sweep in floor beams over piers; Bearing rotations.

Report revised after 7/8/2014 condition assessment of repairs to structure

Former Smart Flag 364 (Steel Out-of-Plane Compression Member) was placed in Condition State 1 with the following note: 'BOTH TRUSS UPPER CHORDS SHOW LOCALIZED MISALIGNMENT NEAR PANEL POINT U3. THE NORTH TRUSS IS DISPLACED 5/8" SOUTH AT U3. THE SOUTH TRUSS IS DISPLACED 1 7/8" NORTH AT U3.' SUPER RATING RAISED FROM 4 TO 5 BY WES KELLOGG 04/12/2016 BASED ON COMPLETION OF REPAIRS AND EVALUATION OF FLOOR BEAM SWEEP.

An OS inspection was performed on November 11, 2016. All previous deficiencies were verified, and the following changes were found:

-Rocker Bearing rotation:

Span 1, Pier 1, East Bearing: 13 degrees expansion (at 60 degrees F)

Span 1, Pier 1, West Bearing: 2.5 degrees expansion

Span 2, Pier 1, East Bearing: 3 degrees expansion

Span 3, Pier 3, East Bearing: 20 degrees expansion (at 69 degrees F)

Span 3, Pier 3, West Bearing: 20 degrees expansion

Span 4, Pier 3, East Bearing: 5 degrees contraction

Span 4, Pier 3, West Bearing: 8 degrees contraction

Span 5, Pier 5, West Bearing: 3 degrees expansion (at 78 degrees F)

Span 6, Pier 5, East Bearing: 6 degrees expansion

Span 6, Pier 5, West Bearing: 8.5 degrees expansion

Section Loss to Gusset Plates:

Span 3, East Truss, L10 exhibits 1/8" section loss along the interface of the lower chord

Inspection notes continued:

-Cracks at stringer copes:

Span 2, Stringer 6, Floor Beam 2, South Face: East Face - 3/8"

Span 2, Stringer 6, Floor Beam 3, North Face: East Face - 1/2" West Face - 3/8"

Span 2, Stringer 6, Floor Beam 6, South Face: 1/2" painted over, but corrosion reactivating

Span 3, Stringer 5, Floor Beam 3, North Face: previously noted 3/4" crack not visible due to new paint

Span 3, Stringer 6, Floor Beam 0, North Face: 1/4"

Span 4, Stringer 6, Floor Beam 4, North Face: previously noted 5/8" crack not visible due to new paint

-Section loss/welded repairs in stringer and floorbeam ends:

Span 1, Floor Beam 1, East Truss connection: corrosion hole 2" L x 1.5" H, with painted over pitting up to 1/8" D

Span 1, Floor Beam 1, Stringer 1, north face: section loss on the underside of the top flange, 6" L x 1" H x up to 3/16" D

Span 2, Floor Beam 7 and Span 3, Floor Beam 0: bottom flanges between the west truss and Stringer 2 have corrosion holes throughout

Span 3, Floor Beam 1, Stringer 6: corrosion hole 1.5" L x 3" H

Span 3, Floor Beam 10: web at the west truss connection has a 7" H x 1" W area of up to 100% painted over section loss. The bottom flange near the west truss has multiple corrosion holes, and bottom of web below stringer 6 has a 1" diameter corrosion hole.

Span 4, Floor Beam 8: north bottom flange is essentially gone due to corrosion from stringer 1-2

Span 5, Floor Beam 0: below stringer 1, web has multiple pin holes and a 2" H x 1-3/4" W corrosion hole

Span 5, Floor Beam 5: corrosion hole 2" in diameter near the east truss connection

-Floor Beam Sweep:

Pier 3: The sweep of both floor beams has increased to 1/4" inward.

Additional  
Elements

Roadway Name : COUNTY ROAD		NBI Information Applicable To The Route Under The Structure		
5. Inventory Route (Route Under Structure :	2 - 4 - 1 - 00000 - 0	102. Traffic Dir.:	2 2-way traffic	
10. Min. Vert. Clr.(ft.):	16.6	104. Highway System :	0 Not on NHS	
12. Base Hwy Network :	Not on Base Network	105. Fed Land Hwy :	0 N/A (NBI)	
13. LRS Inv. Rt./ Subroute :	-1 / -1	109. Truck ADT% :	15	
19. Detour Len.(Mi.):	0.0	110. Natl. Truck Network :	0 Not part of natl netwo	
20. Toll Facility :	3 On free road	114. Future ADT :	160	
26. Function Class.:	07 Rural Mjr Collector	100. Defense Highway :	0 Not a STRAHNET hwy	
Agency Field: 1.(Under Rte.):	U	2.(Vert. X-Ref.):	-1	3.(Compass Dir.): N
		4.(Vert. Post. Inc.):	1411	5.(Vert. Post. Dec.): 1411